


WHAT LIES BENEATH



What you don't see can hurt your Avengers, repairmen. The Avenger swings every which way during operation. Anything sticking up in the cargo wells will gouge or crack the bottom of the turret. Same thing happens if the battery box lid is left up.

If those gouges or cracks aren't found and fixed, they can get worse and become unreparable. That means a new turret.

A great time to check the condition of the bottom of the turret is when support takes off the Avenger for services. While the turret is suspended, check underneath for cracks and gouges.

But even when the turret is installed, you can inspect the bottom perimeter of the turret for problems. That's where you find most gouges and cracks. It's a good check to make after every trip to the field.

